



Final shaping process using 220-400-600 sanding belts to remove flat spots.

2/20/2013

C. K. Grundke

68



Using Dop Stick to Center Belt on Wheel as it slows down.



2/20/2013

C. K. Grundke

69

Use random motion to cover entire cab area on 220 belt



2/20/2013

C. K. Grundke

70



2/20/2013

C. K. Grundke

71

Use reflection of fluorescent lights to check cab



Move to 400 grit belt







**Make sure entire cab surface
has been prepolished .**

