




Layout to draw oval 1/3 size of cab on top of cab






2/20/2013

C. K. Grundke

22



Layout for oval 1/3 the size of cab



2/20/2013

C. K. Grundke

23



Heat Lamp heating Stone & Wax



2/20/2013

C. K. Grundke

26

**If Stone is hot enough to melt wax
It ensures a good bond.**



2/20/2013

C. K. Grundke

27

Apply small amount of wax to end of dop stick.



2/20/2013

C. K. Grundke

28



2/20/2013

C. K. Grundke

29

Attach stick to stone



2/20/2013

C. K. Grundke

30

Align stick vertically from center of stone.



2/20/2013

C. K. Grundke

31





2/20/2013

© K. Brundage

34